



**BUREAU
VERITAS**

PIPE TESTING

Client: Cromford Group Pty Ltd
Address: PO Box 1196
MOSS VALE NSW 2577
Attention: Steve Anderson

Issue Date: 16/07/10
Test Date: July 2010
Report No: 10ARTH1896647
Client Ref: PO No. 11469

Test Specification: AS 2439.1 – 2007
Pipe Type / Classification: Type 1 / Classification SN20
Pipe Diameter: 100mm

Test Results			
Clause	Test	Result	Compliance
5.2	Bending	No splitting or cracking was noted.	PASS
5.3	Straightening	No splitting or cracking was noted.	PASS
5.4	High Temperature Impact Resistance	No splitting, cracking or significant indentation was noted.	PASS
5.5	Low Temperature Impact Resistance	No splitting, cracking or significant indentation was noted.	PASS
5.7	Pipe Stiffness	Stiffness @ 5% deflection	20,621 N/m/m
		Stiffness @ 10% deflection	18,334 N/m/m
			PASS

Testing Officer: Adrian Fahey / Dylan Randall
Status: Materials Testing Officer(s)

Paul Hosking
Technical work coordinator
Materials Services

This report was prepared by Bureau Veritas expressly for the customer as nominated on the front cover. Neither Bureau Veritas nor any person acting in its behalf (a) makes any warranty, express or implied, with respect to the use of any information or methods disclosed in this report or (b) assumes any liability with respect to the use of any information or methods disclosed in this report. Any recipient of this document, by their acceptance or use of this document, releases Bureau Veritas and their affiliates from any liability for direct, indirect, consequential or special loss or damage whether arising in contract, warranty, express or implied, tort or otherwise, and irrespective of fault, negligence and strict liability. Email copies of this report are not official unless authenticated and signed by Bureau Veritas and are not to be modified in any manner without the express written consent of Bureau Veritas. Test samples and off cuts of client test samples sent to Bureau Veritas for investigation will be retained in a weather proof area for approximately one month after the issue of this report and for a further two months in external storage before disposal. If these parts are required by you then you must contact Bureau Veritas to arrange pick up before this term has elapsed. S:\Materials\Auto\10ARTH1896647 Cromford