



Doug Gray
Australian Film & Pipe Manufacturers
PO BOX 1196
Moss Vale NSW 2577

13 October 2009

Dear Doug,

Product approval: 125mm "Waveflow" Profile Wall Smooth Bore Conduit

I refer to your application ID No 1025 and I am pleased to advise that the following product has been approved for the use in the Integral Energy Network.

Product approval no.	Product reference (supplier/ manufacturer catalogue no.)	Approval date	Item description
AN0073A	Waveflow 125mm	13/11/2009	125mm "Waveflow" Profile Wall smoothbore HD conduit

Please be informed that the approval number belongs to the product and hence it is issued to the manufacturer.

This approval is subject to the following conditions:

- You are required to ensure Accredited Service Providers who intend to use/install the product are given adequate training and/or familiarisation of this product.
- Records of all training and familiarisation sessions should be kept and should include:
 - names of the trainers;
 - the date of the training;
 - a list of the names of attendees;
 - the type of training/familiarisation received; and,
 - an acknowledgment by the attendees that they have received and understood the training.

Going further for you is what we do

Contact name Adrian George Direct phone 02 9853 6203 Fax 029853 6021
51 Huntingwood Drive Huntingwood NSW 2148. PO Box 6366 Blacktown NSW 2148. DX 8148 Blacktown
Integral Energy Australia ABN 59 253 130 878 www.integral.com.au



The power is in your hands

- If any changes or modifications that are made to the product, or to any part of the product, the approval is deemed to be null and void unless prior approval in writing is obtained from the Integral Energy for such changes.

- Integral Energy reserves the right to withdraw this approval with immediate effect, in the event of:
 - a) any of the information provided along with the product approval application by the applicant is subsequently found to be incorrect;

 - b) the product fails to satisfactorily perform the intended function and purpose;

 - c) the product fails prematurely when in service, or in any future testing Integral Energy may wish to carry out;

 - d) the product becomes obsolete due to changes to Integral Energy's design standards and practices; or,

 - e) training that is to be provided to ASPs to use/ install the product is found to be inadequate or unsatisfactory.

Yours sincerely



Don Wijayasinghe

Distribution Engineering Manager

Distribution Engineering

In reply please quote application ID: 1025

Copy to: Garry Copas, Purchasing Officer, Huntingwood.
Garry Duffy, Inventory Controller- Glendenning.
Ivan Mendonsa, Contractor Operations Manager – Glendenning.